PPAP Sample Matrix

Step 1. Identify the Part(s) and Supplier

Enter the Part Number and Suffix
15017377
Click
ListDuns Codes

Then choose Duns Code 607396215 ▼
Click fortung to fill Sample Matrix

Step 2. Select the Desired Sample

EXPIRED USABLE	EXPIRED USABLE EXPIRED USABLE	z	XXX 15-JUN-1998	×	0	œ	28-SEP-1998 15:16:15
PROMISED	PROMISED	z]	0	₩	12-OCT-1999 01:44:56
APPROVED	APPROVED	z	13-JAN-1999	900	0		03-SEP-1999 13:58:59
APPROVED	APPROVED	z	012 07-OCT-1999	012	0		30-NOV-1999 10:24:46
APPROVED	APPROVED	z	07-SEP-2001	Wo	•		23-JUL-2002 13:21:48
Semina Sieta	Shipping Status	Multiple Tools	IEGI-IDAIO	ECL.	Master Indicator	Suffix	3 Sample Cresis Date:

Greate Next/Sample

Click Return to the top of this page

PPAP Administrator Master Sample Override:

Move Radio Button to Proper Sample and Select

Toverride Master

PPAP Status Inquiry

View Participup for this Submission

		ction	Production	Phase:	
Receive Date: 23-JUL-2002	Receive Date:	Change	Engineering Change	Submission Reason:	Subn
23-JUL-2002	Sample Create Date: 23-JUL-2002				
HE270	Latest EWO:		23-JUL-2002	Trial Run: NOT MADE 23-JUL-2002	Trial Run:
19991007	Latest Dwg Date:		23-JUL-2002	Match Check: NOT MADE	Match Check:
012	Latest ECL:				
NE003	Sample EWO:	сро	Material: APPROVED 23-JUL-2002 CPO	APPROVED	Material:
07-SEP-2001	Sample Dwg Date: 07-SEP-2001	CPO	Function: APPROVED 23-JUL-2002	APPROVED	Function:
WO	Sample ECL:	СРО	23-JUL-2002	Durability: APPROVED 23-JUL-2002	Durability:
	La Porte		23-JUL-2002		Color Durability: NOT MADE
	Interim Expiration Date:	CPO	23-JUL-2002	Statistical: APPROVED 23-JUL-2002	Statistical:
		CPO	23-JUL-2002	Appearance: APPROVED 23-JUL-2002	Appearance:
	Interim Class:	СРО	23-JUL-2002	Dimensional: APPROVED 23-JUL-2002	Dimensional:
		Inspector			
0	Samples Reqd:		23-JUL-2002	Sample: APPROVED 23-JUL-2002	Sample:
OTTH Z	Layout Area:	Y	23-JUL-2002	Shipping: APPROVED 23-JUL-2002	Shipping:
	Submission Level:	P.O.	Status Date	Status	
					Starus Update

Submission Report Traveler

Add/Promise Line Item

Promise Date Promise Reason Input Date Delete

Enter Tool ID:

And Click Add Multiple Tool

Tool ID Delete

1 of 1