

REASON FOR SUBMISSION (Check at least one) Initial submission Engineering Change(s) Tooling: Transfer, Replacement, Refurbishment Correction of Discrepancy Are polymeric parts identified with appropriate ISO marking codes? 26655 Northline Road Street Address Windsor Machine & Stamping LTD / W739J Organization Name and Supplier/vendor Code Print Name Organization Authorized Signature is each Customer Tool properly tagged and numbered? **EXPLANATION/COMMENTS** REQUESTED SUBMISSION LEVEL (Check one) ff submitted by IMDS, enter Module ID number, version and data transmitted Taylor, ORGANIZATION MANUFACTURING INFORMATION Safety and/or Government Regulation Engineering Change Level Shown on Drawing Number Ford GPPSS1 November 2008 DECLARATION Has customer-required Substances of Concern information been reported? Checking Aid Number BL54-16L554-EAW Additional Engineering Changes Part Name PART INFORMATION Customer Signature Warrant Status: Phasad PPAP MATERIALS REPORTING a/ Non-PPAP indicates/the partitions not satisfy one or more PPAP requirements and is considered incomplete until at PPAP requirements are satisfied. Print Name PPAP Coordinator Level 5 - Warrant with product samples and complete supporting data reviewed at supplier's manufacturing location Level 4 - Warrain and office requirements as defined by customer. Level 3 - Warrant with product samples and complete supporting data submitted to customer Level 2 - Warrant with product samples and finited supposting data submitted to customer Level 1 - Warrant only (and for designated appearance items, an Appearance Approval Report) submitted to customer Tooling Inactive > than 1 year Tooling: Transfer, Replacement, Refurbishment, or additional BRACKET ASY RR WHL SPLS GUARD Ana Chau Michigan Sycal Submitted by IMOS or other customer format: Region Olyfah O Approved PAAP 6L54-16L554-EAW FOR FORD USE ONLY Abnow N/A Postal code O g Checking Aid Engineering Change Level O Rejected Ann Chan e-mail Country ● ₹ The original copy of this document shall remain at the supplier's location while the part is active Date Non-PPAP at Phone No. 519-737-7155 Email O Interim Accepted ğ 124/118 O ₹ achau@windsormachine.com Purchase Order No. 0 George Berletic / GKB5 Buyer/Buyer Code Ford Motor Company Customer Name/Division Application TR3 Ranger CUSTOMER SUBMITTAL INFORMATION Cust. Part Number Organization Part Number appearance otheria OYes ON ® Na 콯 ® Yes ○ Ne Engineering Authorization Other - please specify below Change in Part Processing Supplier or Material Source Change Change to Optional Construction or Material Dalled Parts produced at Additional Location Dated 30605190 Description: (Incomplete PPAP Requirements) interim Status (to be completed by the Organization) 띪 Fax No. 6L54-16L554-EA5YGY ı₹ statistical process package 6/15/05 519-737-7102 6L54-16L554-EA5YGY Alert, Temp. PCM, TPD Number Date Weight (kg) 0.34019 KG 18-Apr-08 1/22/01